



## Full metal top and side entry hoods with knurled screws

Identification      No. of contacts      Part No.      Drawing      Dimensions in mm

D-Sub

**Top entry hood incl. grommet set halves**

Please insert digit for screw option


- Knurled screw, thread 4-40 UNC ▶ 3
- Knurled screw, thread M3 ▶ 8

9	09 67 009 034
15	09 67 015 034
25	09 67 025 034
37	09 67 037 034
50	09 67 050 034

Poles	A	B	C	D	E
9	31.0	39.5	14.8	25.0	11.7
15	39.5	41.5	14.8	33.3	11.7
25	53.5	48.5	14.8	47.0	11.7
37	71.0	53.0	14.8	63.5	11.7
50	67.5	54.0	18.7	61.1	17.0

Spare knurled screw thread 4-40 UNC thread M3

09 67 002 9029
09 67 002 9101



**Side entry hood incl. grommet set halves**

Please insert digit for screw option


- Knurled screw, thread 4-40 UNC ▶ 3
- Knurled screw, thread M3 ▶ 6

9 <sup>1)</sup>	09 67 009 033
15	09 67 015 033
25	09 67 025 033
37	09 67 037 033
50	09 67 050 033

Poles	A	B	C	D	E
9	31.0	37.7	14.7	—	11.7
15	39.5	42.0	14.7	33.3	11.7
25	53.2	41.3	14.7	47.0	11.7
37	69.7	41.8	14.7	63.7	11.7
50	67.4	44.9	17.4	61.1	17.0

Spare knurled screw thread 4-40 UNC thread M3

09 67 002 9028
09 67 001 9997



**Spare grommet set halves**

9-37 poles

09 67 002 9092
----------------

50 poles

09 67 002 9094
----------------

Grommet dimensions		
Number	Diameter F	
	9-37 poles	50 poles
1	4.0	15.0
2	5.0	14.0
3	7.0	12.5
4	9.0	11.0
5	10.2	—

<sup>1)</sup> 9-pole hood provided with only one screw on the opposite side of the cable entry.  
Operating temperature for all hoods on this page: -40 °C ... +120 °C