



# **Combination Photo Tachometer/Stroboscope**

**2 meters in one - Stroboscope to analyze rotating objects** Plus a Non-Contact Tachometer to measure rpms

#### **Features:**

- Unique display where characters reverse direction depending on measurement mode you are in
- Large 0.4" 5 digit LCD digital display
- Microprocessor based with quartz crystal oscillator to maintain high accuracy
- Tachometer memory stores last, max and min readings
- Performs Tachometer RPM measurement and Stroboscopic speed and motion analysis
- Stroboscope course and fine flash rate adjustments in three ranges
- · Battery operation brings motion analysis to any location
- Complete with four 1.5 volt AA batteries, reflective tape and carrying case



Photo	Strobe
0.5 to 20,000	5 to 99,999
	±(0.1% +2digits)
0.2 to 6560 ft/min	
1 sec > 6  RPM	1 Sec $\geq$ 60 RPM
0.1 RPM (<1,000 RPM)	0.1 FPM (<1,000 FPM)
1 RPM ( $\geq$ 1,000 RPM)	1 FPM (≥1,000 FPM)
4 x 1.5V AA Batteries	
8.5 x 2.6 x 1.5" (215 x 65 x 3	8mm)
10.6oz (300g)	
	0.5 to 20,000 0.2 to 6560 ft/min 1sec > 6 RPM 0.1 RPM (<1,000 RPM) 1 RPM ( ≥ 1,000 RPM) 4 x 1.5V AA Batteries 8.5 x 2.6 x 1.5" (215 x 65 x 36

### **Ordering Information:**

461825 ......Combination Tachometer/Stroboscope 461825-NIST ......461825 with NIST certificate 461937 ......Spare Reflective Tape (23" each strip),10pk

## 1.800.561.8187



## information@itm.com