## Tools for contacts Han D<sup>®</sup> (09 15 ...)



Identification	Part number	Drawing Dimensions in mm
Insertion tool for crimp contacts	09 99 000 0059	For crimp contacts with wires of less than 0.75 mm² it is recommended that an insertion tool is used. Contacts should be inserted from the wiring side and pushed down until a positive locking is achieved.
Removal tool for crimp contacts		
Removal tool	09 99 000 0012	
Replacement-tip for removal tool	09 99 000 0004	
Removal tool	09 99 000 0052	
		A removal tool is necessary if contacts are to be replaced in the insert. It is inserted from the mating face and pushed over the contact until a stop is noticeable. Additional pressure unlocks the contact and pushes it out of the wiring side. In case of the removal tool ( 0052) the unlocking process is achieved by pressure on the central rod.